


HRS and GPS laser windows:

HRS:


O-rings:

Window
(march 2005 – march 2007):

Bouchon o-ring:




Window o-ring:




Example of a dirty window september 2007:

(march 2007 – 14 Sept 2007):



GPS:

O-ring:



Window
(march 2005 – march 2007):

